


To: [redacted] (SPLQS) - KLM [redacted]@klm.com]; [redacted] (SPLFW) - KLM [redacted]@klm.com]; [redacted]@worldcourier.nl]; [redacted] (PH) - KLM [redacted]@worldcourier.nl]; [redacted]@worldcourier.fr]; [redacted]@worldcourier.nl]
Cc: [redacted] (CASD PH) - KLM [redacted]@klm.com]; [redacted]@rivm.nl]; [redacted]@worldcourier.co.uk]; [redacted]@worldcourier.nl]
From: [redacted]
Sent: Fri 2/19/2021 2:20:15 PM
Subject: RE: Temp deviation BON shipment (074-42488423)
Received: Fri 2/19/2021 2:20:17 PM

Hi [redacted]
Thanks for the overview; we also had shipment to Aruba on same flight (074-42488412).
Was the AUA shipment also loaded in dedicated AKE container? On which a/c position was the AUA shipment loaded?

Rgds, [redacted]



De volgende 18 pagina's zijn verwijderd i.v.m. dubbel.