 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 1 of 23		

TO: ADM Promotions Hong Kong Ltd

FROM: BM Inspection Division

ATTN: 5.1.2e

ATTN: 5.1.2e

Inspection Profile

Buyer Name	ADM Promotions Hong Kong Ltd	Product Image (front view) 
Vendor Name	MU(1931) Limited	
Factory Name	Jiangsu Nanfang Medical Co.,Ltd	
Article Number	SHMUN95	
Product description	FFP2-MASKS-EN149:2001+A1:2009	
P.O. Number	578977	
Total Inspection Quantity	221040pcs(307ctns)	
QAP doc. Number	TRD070420D0228A	
Service Type	FRI	
Inspection Date	Apr 28, 2020	
Inspection Location	Changzhou, Jiangsu, China	

Inspection Summary

Attributes	Result	Special Attention	Informative Remark
Section 1: Workmanship	Conformed	-	-
Section 2: Quantity Conformity	Conformed	-	-
Section 3: Product Conformity	Conformed	-	-
Section 4: Packing / Marking / Labeling	Conformed	-	Point 4.2.1
Section 5: Data Measurement / On-site test	Conformed	-	Point 5.2.1

Special Attention


Nil

Informative Remark

4.2.1 Carton with metal staple, it was accepted by client.
5.2.1 One shipment sample was sealed and would be send to client.

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 2 of 23		

Result:
Conformed

Section 1: Workmanship

Standard adopted: Single sampling plan for Normal inspection: ISO2859-1:1999 Special sampling level: S-4 Sample size: 125 units (80 out of 125 for major , minor inspection)		AQL: Critical Safety : Not allowed Critical Function: 0.4 Critical Function + Major: 1.0 Minor: 2.5			
Item No.	Defect Description	CRS	CRF	CRF+MAJ	MIN
SHMUN95	Wrinkle on surface	-	-	-	2
	Dirty mark	-	-	-	2
Total Found		0	0	0	4
Max. Allowed		0	1	2	5



1.1 Special Attention

Nil

1.2 Informative Remarks


Nil


1.3 Defect Photos

	
Wrinkle on surface -minor	Wrinkle on surface-minor

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2 style="margin: 0;">Inspection Report</h2>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 3 of 23		

	
Dirty mark -minor	Dirty mark-minor

Section 2: Quantity Conformity

Result:
Conformed

PO No.	Item No.	Order Qty.		Quantity available(units)			Sample size(units)	
		Units	CTNs.	Packed	Not packed	Not finished	Packed	Not packed
578977	SHMUN95	221040	307	221040	0	0	125	0
Total:		221040	307	221040	0	0	125	

2.1 Special Attention

Nil

2.2 Informative Remarks

Nil

Section 3: Product Conformity

Result:
Conformed

1	Product Specification(Size/Color/Style) Conformity	Conformed
2	Gold Seal Sample Conformity	Conformed
3	Instruction Manual Conformity	Not Available

3.1 Special Attention

Nil

3.2 Informative Remarks


Nil

Section 4: Packing / Marking / Labeling

Result:
Conformed

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 4 of 23		

1	Packages Conformity	Conformed
2	Shipping Marks Conformity	Conformed
3	Labeling Conformity	N/A
4	Barcode Conformity	N/A

4.1 Dimension & Gross Weight

Item No.	Attribute	Qty per CTN	Qty per INNER	Cardboard (3/5/7-Ply)	Dimensions (L x W x H cm)	Gross weight (Kgs)
SHMUN95	Outer carton	720pcs	30pcs	5-Ply	60*34.5*36cm	6.405kgs

4.1 Special Attention

Nil

4.2 Informative Remarks

Point 4.2.1

Section 5: Data measurement / On-site test

Result:
Conformed

No.	Test Item	Samples	Requirement	Test Result
1	Carton number check	Whole lot	All master carton must filled with carton number.	N/A as not required for this shipment.
2	Carton transit drop test	1ctn	1 corner, 3 edges, 6 panels, 10 times drop on concrete floor 66cm. No broken of product and package.	Conformed
3	Product size check	13pcs	155*105mm +/-3%	Conformed
4	Product net weight	13pcs	6.4g, No less than 6g.	Conformed
5	Product fitting check	3pcs	Must fit the adult's head, easy to wear and remove, 25 cycles per minute, 20 minutes, cannot be damaged.	Conformed
6	Nose clip check	8pcs	Each mask must be equipped with a nose clip, folded 10times repeatedly, and must not break.	Conformed
7	Mask straps check	8pcs	Apply a 10N pull, the mask strap and the body cannot be detached. Stretch length should not be less than 2 times the length.	Conformed
8	Flame retardant check	3pcs	After leaving the flame, continue to burn no more than 5seconds.	Conformed
9	Fabric humidity check	13pcs	Must under 10%.	Conformed
10	Unit quantity in package check	3ctns	5pcs per polybag, 30pcs per inner box, 720pcs per carton.	Conformed
11	Material odor test	125pcs	Without any pleasant odor when open the package and product.	Conformed

5.1 Special Attention


Nil

5.2 Informative Remarks

Point 5.2.1

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong





The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result
		Report Date:	Apr 29, 2020	
		Page 5 of 23		

Attachment Photos


1 Package and Product Photos


SHMUN95

 <p>2020/04/28</p>	 <p>2020/04/28</p>
Master carton view	Carton marking on wide side
 <p>2020/04/28</p>	 <p>2020/04/28</p>
Carton marking details	Carton marking on narrow side


Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2 style="margin: 0;">Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 6 of 23		



Carton marking details



Carton marking on top



Carton packing method



5-ply




Carton packing



24 color box per carton

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h1>Inspection Report</h1>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 7 of 23		




Color box packing




Color box top view



Front panel view



Marking details




Marking details




Marking details


Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.


 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; text-align: center; font-weight: bold;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 8 of 23		



Side panel view



Marking details



Marking details



Color box bottom




Product packing



Product packing

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 <p>BENCHMARKS Since 1993 Your Partner in the Supply Chain</p>	<h1>Inspection Report</h1>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 9 of 23		



Quality pass card



Polybag packing



Product packing



Product packing




Poly bag view









Warning on poly bag

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong


The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 10 of 23		

 <p style="text-align: right; color: red;">2020/04/28</p>	 <p style="text-align: left; color: red;">2020/04/28</p>
5pcs per poly bag	Product view
 <p style="text-align: right; color: red;">2020/04/28</p>	 <p style="text-align: right; color: red;">2020/04/28</p>
Product view	Product view
 <p style="text-align: right; color: red;">2020/04/28</p>	 <p style="text-align: right; color: red;">2020/04/28</p>
Product view	Product details

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 11 of 23		



Product details



Product details



Product details



Product details




Sample comparison






Sample comparison

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.


	<h2 style="margin: 0;">Inspection Report</h2>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 12 of 23		

	
Sample comparison	Sample comparison
	Nil
sample signature	Nil

2 Data Measurement and On-site Test Photos

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 13 of 23		



Carton gross weight



Carton length measurement



Carton length measurement



Carton length measurement




Carton width measurement



Carton width measurement

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS Since 1993 Your Partner in the Supply Chain	<h1>Inspection Report</h1>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 14 of 23		



Carton height measurement



Carton height measurement



1 color box weight



1 color box weight




Color box length measurement



Color box length measurement


Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 <p>BENCHMARKS Since 1993 Your Partner in the Supply Chain</p>	<h1>Inspection Report</h1>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 15 of 23		



Color box width measurement



Color box width measurement




Color box height measurement



Color box height measurement




5pcs weight



5pcs weight

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2 style="margin: 0;">Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 16 of 23		



Product net weight



Product net weight



Product net weight



Product net weight




Product size check



Product size check

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 <p>BENCHMARKS Since 1993 Your Partner in the Supply Chain</p>	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 17 of 23		



Product size check




Product size check



Product size check




Product size check



5.1.2e

Mask fitting check	Mask fitting check
--------------------	--------------------

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong
 The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

	<h1>Inspection Report</h1>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 18 of 23		




Ear strap strength test 1kgs weight



Ear strap strength test 1kgs weight 1minute, ok



Structure layers check



Nose clip




Nose clip length 10cm



Nose clip bending life test

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

	<h2 style="margin: 0;">Inspection Report</h2>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 19 of 23		



Nose clip bending life test



5layers mask



Fabric density check



Outside layer non-woven waterproof check




Middle layer meltblown electrostatic adsorption test



Middle layer meltblown melt , not burnt

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2 style="margin: 0;">Inspection Report</h2>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 20 of 23		



Middle layer meltblown melt , not burnt



Basic check for each ear strap strength



Fabric humidity check



Fabric humidity check




3M test



3M test

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

	<h1>Inspection Report</h1>	Report No.:	TJ200400683	Overall Result PASS
		Report Date:	Apr 29, 2020	
		Page 21 of 23		




Middle layer meltblown fabric electrostatic adsorption test



Middle layer meltblown fabric electrostatic adsorption test



Middle layer meltblown fabric electrostatic adsorption test



Material odor test




Carton drop test



Carton drop test

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong
 The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.


 BENCHMARKS <small>Since 1993</small> Your Partner in the Supply Chain	<h2>Inspection Report</h2>	Report No.:	TJ200400683	Overall Result <div style="background-color: green; color: white; padding: 5px; font-weight: bold; font-size: 1.2em;">PASS</div>
		Report Date:	Apr 29, 2020	
		Page 22 of 23		

3 Other Photos(Storage, Sample Comparison)

 <p style="text-align: right; color: red; font-size: small;">2020/04/28</p>	 <p style="text-align: right; color: red; font-size: small;">2020/04/28</p>
Factory gate	Factory building
 <p style="text-align: right; color: red; font-size: small;">2020/04/28</p>	 <p style="text-align: right; color: red; font-size: small;">2020/04/28</p>
Packed goods in warehouse	Packed goods in warehouse

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

	<h3>Inspection Report</h3>	Report No.:	TJ200400683	Overall Result
		Report Date:	Apr 29, 2020	
		Page 23 of 23		

	
Sealed shipment samples to client	Sealed shipment samples to client

-----The End-----

Address: Unit 20,5/F., Block B, Proficient Industrial Centre, 6 Wang Kwun Road, Kowloon Bay, Hong Kong

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.